# VPOD Vertical Cable Mgmt Fingers Installation





**Parts Description**

VPOD Vertical Cable Management Fingers
(4) Phillips Head Screws
(4) Plastic Cup Washers

**Required Tools**

#2 Phillips Screw Driver



**1** Locate the cable management fingers onto the frame rails as shown.

*NOTE: The fingers should be oriented so that the fingers point to the outside of the cabinet as shown.*



**2** Secure the Cable Management Fingers to the frame rail using the 2 – Phillips Head Screws and plastic washers as shown.

**To assist safe installations, comply with the following:**

A. Use caution when installing or modifying telecommunications circuits.

B. Never touch uninsulated wire terminals unless the circuit has been disconnected.

C. Never install this device in a wet location.

D. Never install wiring during a lightning storm.

**SIEMON**

**www.siemon.com**