



March 22, 2019

## **POWERMAX FIRMWARE VERSION 1.3.1**

### **COMPATIBLE WITH:**

- Siemon PowerMax Vertical Intelligent PDUs running version 1.2.0, 1.2.1 and 1.3.0:
  - Monitored - 8MV(XX)-(XX)(XX)(X)-(X)(X)(X)
  - Smart - 8NV(XX)-(XX)(XX)(X)-(X)(X)(X)
  - Switched - 8SV(XX)-(XX)(XX)(X)-(X)(X)(X)
  - Managed - 8WV(XX)-(XX)(XX)(X)-(X)(X)(X)

### **UPDATES FROM 1.3.0:**

#### IMPROVEMENTS:

- Added the ability to cycle the time schedule settings to enable outlet power to be cycled to outlets on a repeated daily schedule.

### **INSTALLATION NOTES:**

**WARNING:** Allow at least 5 minutes for the firmware upload and installation to the unit before interacting with the PDU. Interrupting the firmware installation can cause permanent damage to the PDU controller.

It is recommended to create a backup the PDU settings prior to carrying out the update as the PDU may reset to factory settings during the firmware update.

Refer to section 3.3.7 of the PowerMax Installation Instructions for update instructions. Once the PDU is updated – the browser cache should be cleared by following these steps:

Internet Explorer: Options>Safety>Delete browsing history. Ensure that temporary internet files and cookies are checked.

Chrome: Options>More tools>Clear browsing data. Advanced. Ensure that Cookies and other site data and Cached images and files are checked.

Firefox: Navigate to the history menu>Clear recent history. Expand details and ensure that Cookies and Cache are selected along with an appropriate time range.

For any more assistance or support please contact your regional Technical Support Representative.