


# Supplemental Z-Plug Termination Instructions – OSP shielded cable preparation

Alternate Step 2 cable prep for OSP category 6A shielded (S/FTP) cable



\* Refer back to Z-Plug Termination Instructions 100.24877.00

Continue To Step 3 \*

2017 Siemon Rev.A Oct. 2017

Global Headquarters  
Watertown, Connecticut USA  
Tel: (1) 866-548-5814



For a complete listing of our global offices visit our web site