


INSTRUCTIONS FOR RACK HINGE RHNG-2, -3



FIGURE 1 - (TOP VIEW) ASSEMBLING THE HINGE TO THE MOUNTING RACK.



1. MOUNT HINGE TO THE LEFT OR RIGHT SIDE OF AN EIA MOUNTING RACK.
 2. USE THE MOUNTING SCREWS INCLUDED TO SECURE THE BENT EDGE OF THE HINGE TO THE RACK AS SHOWN IN FIGURE 1.
 3. USE THE TWO STAND-OFFS INCLUDED TO OFFSET THE PANEL .50 (12.7mm) AT THE OPPOSITE END OF THE MOUNTING RACK AS SHOWN IN FIGURE 2.
 4. SCREW THE PANEL TO THE HINGE AND STAND-OFFS AS SHOWN IN FIGURE 2.
 5. MOUNTING CAPABILITIES FOR SIEMON COMPANY PANELS:
 - RHNG-2:
 - ONE 2RMS (24 OR 32 PORT) PANEL
 - TWO 1RMS (12 OR 16 PORT) PANELS
 - TWO HINGE ASSEMBLIES MAY BE COMBINED TO MOUNT ONE 4RMS (64PORT) PANEL.
 - RHNG-3:
 - ONE 3RMS (48 PORT) PANEL WITH ANSI MOUNTING SLOTS.
 - ONE 3RMS PANEL WITH 3.00" (76.2mm) MOUNTING SLOTS.***
 - TWO HINGE ASSEMBLIES MAY BE COMBINED TO MOUNT ONE 6RMS (96PORT) PANEL.
- ALL MOUNTING LOCATIONS CONFORM TO ANSI/EIA ES-310-C-77 & MIL-STD 189 STANDARDS EXCEPT ***

FIGURE 2 - (TOP VIEW) ASSEMBLING THE PATCH PANEL TO THE RACK HINGE.

